EXECUTIVE RISK ASSESSMENT SUMMARY

HAZARD REPORT NUMBER: LWS-MS-ERAS-3B	DATE: 12/95	
REV. LETTER:	REV. DATE:	
PART NUMBER: 950001-25	LRU NUMBER: SED39126815	
TITLE: Unable to restrain crew member.	1. SEVERITY: Catastrophic	
	2. LIKELIHOOD OF OCCURRENCE Improbable	
	3. CLASSIFICATION: Controlled	
CAUSE:	REDUNDANCY SCREENS:	
B. Restraint system release buckle internal mechanism fails.	A - Pass	
	B - Pass	
	C - Pass	
FMEA: LWS-MS-ERAS-3B Criticality: 1R/2	. <u> </u>	
Name/Quantity: Restraint release buckle/1		
unction. Restrain crew member in the seat		
ailure Mode:	Cause: Excessive wear, piece-part defect,	
internal buckle mechanism fails to hold each restraint	vibration	
harness belt in place or inadvertently releases all belts.		
	Failure detection: Crew member notices release of a beh.	
Corrective Action: Crew will rebuckle loose belt.		
EFFECT.	REMAINING PATHS:	
Time to Effect: Immediate	None	
Time to Correct: Seconds		
ailure Effect:		
Restraint system inadequate to provide support/ restraint for	r nominal flight loads or crash loads. Possible crew injury/	
oss of crew due to crewmember being tossed during turbule	ence, landing or following a failure which results in a crash	
anding		
CONTROL/RETENTION RATIONALE:		
Functional test performed before and after each cerufical	tion tost PDIA (CKD:0126434) PIA (EX D:012625) and	
DMRS (File 3 V66AAO) with QA participation during each	h certification test. PDA and PIA	
. Restraint system harness will be designed to withstand vi	hrations accorded with Laureh DTI 5 and I sad	
. Designed for minimum access for contamination.		
Even though the loss of a belt could result in injury to the	crew during a crash, it has been determined that in a crash	
ituation that the restraint provided by the remaining balls of	will provide some level of protection and is considered better	
han no restraint at all.	and breaking source level of blodecinon and is considered better	
ERIFICATION:		
	shoulder and lap belts will release from the buckle. With a	
mall preload on the barness everem 20 ±/. 2 mounts	snowner and Jap bens will release from the buckle. With a se the fittings from the buckle by using one hand and turn th	
process of the materies sinceric 20 -/- 2 pounds, release	se one ritarize from the buckle by fixing one hand and firm ()	

- buckle release clockwise. Repeat for counter-clockwise.
- 1b. OMRS V66AA0.052-A. 053-A. 054-A. 055-A, 056-A Verify locking mechanism of harness buckle
- 2. A vibration test has been performed (QVT TPS FV9520103) to the acceptance levels listed below and reviewed by EM2:

Frequency Range (Hz)	Level			
20	0.00053 g2/Hz	1000	0.030 g2/Hz	Overall = 6.1 grms
150	0.030 g2/Hz	2000	0.0075 g2/H ₂	
350	0.030 g2/Hz		~	

5 During assembly all parts are checked to be clean.